

FREEZE 12[®] Pressure Temperature Chart

°F	FREEZE 12 [®]	CFC-12	HFC-134a
0	4.8	9.2	6.5
5	6.2	11.8	9.1
10	9.8	14.7	12.0
15	11.5	17.7	15.1
20	18.1	21.1	18.4
25	23.3	24.6	22.1
30	26.5	28.5	26.1
35	30.2	32.6	30.4
40	34.0	37.0	35.0
45	39.5	41.7	40.1
50	43.1	46.7	45.4
55	48.3	52.1	51.2
60	55.5	57.7	57.4
65	60.0	63.8	64.0
70	67.4	70.2	71.1
75	75.0	77.0	78.6
80	80.6	84.2	86.7
85	89.1	91.8	95.2
90	95.4	99.8	104.3
95	102.2	108.2	113.9
100	116.7	117.2	124.1
105	125.0	126.5	134.9
110	135.1	136.4	146.4
115	145.6	146.8	158.4
120	157.0	157.6	171.1
125	165.1	169.0	184.5
130	183.3	180.9	198.7
135	189.9	192.9	213.5
140	211.8	206.5	229.3
145	219.2	219.5	245.6
150	243.2	234.5	263.0
155	251.6	248.6	281.0
160	277.8	265.0	300.2
165	287.2	280.2	319.9

170	315.6	298.2	341.0
175	326.4	319.7	362.7
180	347.4	338.7	385.6
185	369.4	358.6	409.7
190	392.4	379.5	434.9
195	416.5	401.2	461.3
200	441.6	420.8	488.9
205	467.9	444.1	518.0
210	480.1	468.4	548.2
215	508.2	493.9	580.3
220	537.8	520.7	613.4
225	567.9	548.2	648.5